



Dr. John Scheirs Litigation Experience 2002-Present

<b>Legal Firm</b>	<b>Nature of Job</b>
Anderson Rice Lawyers , Level 10, 555 Lonsdale Street, Melbourne, VIC 3000.	Heat Seal Failures of Rice Bags
Australian Government Solicitor, HOBART TAS 7001	Biodegradability of disposable nappies
Clayton Utz, 333 Collins Street, Melbourne VIC 3000	Polypropylene Geomembrane failure
Clayton Utz, 333 Collins Street, Melbourne VIC 3000	MDPE Gas pipe failure (squeeze off)
Corrs Chambers Westgarth, Bourke Place, 600 Bourke Street, Melbourne VIC 3000	Biodegradability of PE-starch films
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure analysis of crosslinked polyethylene water pipes
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure analysis of Polyacetal Automotive Door Mechanism Plate
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure Analysis and Investigation of Yogurt Tubes
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure Analysis of PVC Water Filer Housing
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure analysis of flat bread pouches
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure analysis of barrier antipasto thermoformed trays
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Failure analysis of leaking Indian curry sauce pouches
Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC	Analysis of failure of adhesive of foam underlay to wooden floor boards
Davies Collison Cave Solicitors Pty Ltd	Thermoformability of Plastic

1 Nicholson Street , Melbourne VIC 3000	
Deacons, Level 24, 385 Bourke Street, Melbourne VIC 3000	Failure of fPP Grain Covers
Deacons, Level 24, 385 Bourke Street, Melbourne VIC 3000	Failure of Cracked Nitrile Rubber Liner
Deacons Lawyers, Level 17, 175 Eagle Street, Brisbane QLD 4000	Failure of PP-R water pipe
Ebsworth & Ebsworth, GPO Box 4542, Melbourne	Failure of Blow Moulded HDPE Pool Filters
UNSW Global Pty Limited	Failure of Plastic Exercise Balls
Freehills, Level 38, Central Plaza One, 345 Queen Street, Brisbane QLD 4000	Failure of Jumping Castle Material
Freehills, 101 Collins St., Melbourne, VIC 3000, GPO Box 128A, Melbourne	Failure of Plastic Containers for Organic Liquid Peroxide
Gadens Lawyers, GPO Box 129, Brisbane 4001	Failure of ASA Pool Fence
Gilshenan & Luton Lawyers Brisbane Queensland 4001	Patent dispute involving bubble wrap insulation
Louis Gross & Associates, Barristers & Solicitors, Level 17, 390 St Kilda Road, Melbourne, VIC 3004	Oxo-degradable Nappy Sacks
LegalIT Lawyer, Level 30, AMP Place, 10 Eagle Street, Brisbane, Qld 4001	Perforated PVC film
Mallesons Stephen Jaques, Level 50, Bourke Place, 600 Bourke St., Melbourne VIC 3000	Failure of Plastic Truck Air Intake
Mallesons Stephen Jaques Level 60, Governor Phillip Tower, 1 Farrer Place, SYDNEY, NSW	Failure of Gastric Lap Band
Mark Hodges, Solicitor & Attorney, Level 1, 154 Elizabeth St., Sydney NSW	Failure of Fibreglass Composite Water Lift Muffler
Meerkin & Apel Lawyers, 46 Caroline Street, South Yarra Vic 3141	Recycling Process for Medical Waste
Middletons Lawyers,	Failure of Hair Cream tubes

Level 29, 200 Queen St, Melbourne VIC 3000	
Middletons Lawyers, Level 29, 200 Queen St, Melbourne VIC 3000	Failure of HDPE liner in Uranium SX plant
Minter Ellison Lawyers, GPO BOX 1272 Adelaide SA 5001	Failure of ABS Water Filter Housing
Minter Ellison Lawyers Rialto Towers, 525 Collins Street., Melbourne VIC 3000	Failure of Nitrile rubber tank liner
Moray & Agnew Solicitors, Level 8, 440 Collins Street, Melbourne VIC 3000	Failure of Nitrile rubber tank liner
Trade Marks Attorney Norton Gledhill Commercial Lawyers, Level 23, 459 Collins Street Melbourne Vic 3000	Composition of Polyurethane glove
Peter Black & Associates Level 8 114 William Street, MELBOURNE VIC 3000	Failure of HIPS Layer Pads
Phillips Fox, 120 Collins Street, Melbourne 3000	Failure of Flexible PP Liner
Phillips Fox, 120 Collins Street, Melbourne 3000	Failure of Epoxy Phenolic Can Coating
Piper Alderman Lawyers, Level 24, 385 Bourke Street, Melbourne VIC 3000	Cause of Defects in Blown Film
Piper Alderman Solicitors, Level 24, 385 Bourke Street, DX 30829 Collins Street Melbourne	Defects in Rotomolded Polyethylene Water Tanks
Phillips Ormonde Fitzpatrick, 367 Collins St., Melbourne 3000	Failure of Corian Tables
Trivett Keating Solicitors, PO Box 678, Wodonga VIC 3689	Failure of EPDM tank liner
NSG Expert Opinion Services, Rupert Myers Building, Gate 14, Barker Street, UNSW, SYDNEY, 2052	Failure of Recycled Plastic Irrigation Pipe
Expert Opinion Services , A division of New South Global Pty Limited, Rupert Myers Building UNSW NSW 2052 DX 957 SYDNEY	Failure of PVC/nitrile solar heating collectors
NSG Expert Opinion Services, Rupert	Failure of Polyethylene-aluminium foil

Myers Building, Gate 14, Barker Street, UNSW, SYDNEY, 2052	roofing insulation
UNISEARCH LIMITED, Rupert Myers Building, Gate 14, Barker Street, UNSW, SYDNEY, 2052	Failure of Rubber Automotive Tyre
Wotton Kearney, Level 13 28 O'Connell Street, DX 10465, Sydney NSW 2000	Failure analysis of polycarbonate water bottles